

General Environmental Incident Summary

Incident: 3934 **Date/Time Notice:** 10/13/2015

DEM Incident No:

Responsible Party: Tesoro Logistics

Date Incident: 10/1/2015

Time Incident: 1530

Duration:

County: Dunn

Twp: 146

Rng: 96

Sec: 14

Qtr:

Lat: 47.76298

Long: -102.81820

Method: Navigation quality GPS

Location Description: From Killdeer travel south on Highway 22 to 7th St. SW. Turn west, travel 2.9 miles. Turn left (south) and travel 1 mile to location.

Submitted By: Chris Gitch

Affiliation: HES Professional- Marathon Oil

Address: 3172 Hwy 22 N.

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person: Mark Glaser

2972 108S Ave SW

Dickinson, ND 58601

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 1.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

While commissioning a lateral on the Connolly Gathering System, a gate valve on the LACT was not fully closed releasing 1 bbl of crude oil onto the well pad. A 100 gallon tank used to catch oil being bled off over flowed. Oil was contained within the working surface of the well location No impacts to surrounding well site soil, surface water, or ground water.

Risk Evaluation:

No immediate risk. No atmospheric hazards or potential for fluids to contact soil/ground off of location.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

No impact to surface water or ground water. Spill contained on location and contaminated soil is being cleaned up.

Action Taken or Planned:

Spill was contained to the well site pad. Contaminated soil and material were removed using a spill cleanup company contracted by Tesoro. Soil was excavated using a hydrovac and disposed of at a Tesoro approved facility (Clean Harbors)

Wastes Disposal Location: At a Tesoro approved facility. (Clean Harbors)

Agencies Involved:

Updates

Date: 10/13/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Volume:

Notes:

Release, due to an open gate valve on the LACT unit, released 1 barrel of oil onto the well pad according to the report. Will forward to NDIC and follow up if inspector discovers release has moved off the well pad.